

CDF Operations Report

JJ Schmidt 26-July-2004 All Experimenters' Meeting



Store Summary (7/05-7/11)

| Store | Start Date | Duration (hours) | Inst Lum Initial e30 cm-2 s-1 | Int. Lum Delivered nb-1 | Live Lum nb-1 | Tevatron Terminate |
|-----------------------|---------------|---------------------|-------------------------------|-------------------------------|------------------|------------------------|
| 3661 | 7/18 | 35.1 | 79.3 | 3,549 | 3,164 89% | OK * |
| 3663 | 7/20 | 32.6 | 97.9 ⁺ | 3,863 | 2,993 78% | OK |
| 3665 | 7/21 | 29.0 | 92.9 + | 3,702 | 2,947 80% | Quench* (dipole trims) |
| 3671 | 7/24 | 25.2 | 29.0 and 66.1 | 2,905 | 2,517 87% | OK |
| 3674 | 7/25 | | 87.5 | >3,000 | Just ended store | |
| Total 3661-3671 | | 122.0 | | 14,020 | 11,620 83% | |
| FY2004 (3033-3671) | 11/22/03 | 3,294 | | 298,312 | 234,804 79% | |

⁺ Mixed Mode Shot

[•]Store 3661 quenched during end-ofstore study. (Silicon OK..)

[·]Store 3665 quench - Silicon OK



Store Notes

- Including store 3674, CDF accounting shows over 300 pb-1 delivered in FY2004!
- Store 3663 (78% live) Large spike in proton losses tripped muon wire chambers and preceded failure of readout board for COT; RF trip caused high abort gap losses; TEL trip also caused proton losses (unusual).
- Store 3665 (80% live) Proton losses too high to turn on wire chambers first 25 minutes of store; one hour of downtime while we upgraded COT gas plumbing to support Argon-Ethane- O_2 (as opposed to Argon-Ethane-Air)
- (Despite above, proton losses and abort gap losses were generally very good. Out biggest beam concern at moment is stores with large and/or frequent spikes in proton losses.)



CDF STATUS

- CentralOuterTracker status (reverse-aging status)
 - Currents/gains continue to stay at levels from early in run.
 - Getting reading to switch from Argon-Ethane-Air to Argon-Ethane- O_2
 - COT test chamber shows wires are probably really cleaned and not just more conductive good news!
 - Kevin Burkett (COT group) is "guest" Operations Manager this week and promises to show a few slides on COT next week.
- Tevatron beam conditions have been generally acceptable for Silicon detectors.
- Current trigger table has high DAQ deadtime at initial luminosities over 100E30 but deadtime less than 5% integrated over store. No complaints from CDF on the mixed-mode shots.